



QUALITY ASSURANCE DIMENSIONAL INSPECTOR WITH CMM EXPERIENCE

Candidate must have at least 10 years' experience in quality assurance dimensional inspections. Must have documented experience programming and operating the CMM (Coordinate Measuring Machine) and/or a portable measurement device such as a Romer Arm and associated software programs such as PC-dmis. Candidate is required to have the ability to properly operate hand tools such as calipers, various micrometers, height gages, thread gages and strong working knowledge of GD&T (Geometric Dimensioning and Tolerancing). Documented GD&T training is desired. Candidate must be able to interpret engineering drawings and specifications related to Naval and Commercial products.

MUST BE A U.S. CITIZEN FOR THIS POSITION.